

20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
511 PRINCELAND CT.
CORONA, CA

First day on the job we clean, and power wash the existing roof system.



All dirt and loose granules must be removed to get the proper adhesion.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
CORONA, CA

All dirt and debris is being washed from the roof.



Once completely dried we can start applying the bleed block primer.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
CORONA, CA

Applying the bleed block primer at a rate of one gallon per every
100 square feet.



The roof system is being primed and made ready for the repairs.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



AUDRA
CORONA, CA

Once the primer is completed we will start applying the Silicone mastic to all penetrations on the roof.



Exiting roof system will be completely primed by the end of the day.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
CORONA, CA

Existing roof system is almost completely primed.



Once primed we will start the Silicone mastic.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
CORONA, CA

All expansion joints in the parapet walls are being resealed using Silicone mastic. Top of sheet metal reglet flashing is also being sealed.



All duct work shall be resealed, primed, and coated with Silicone.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879

SolarEx

ADURA
CORONA, CA

All vertical laps on the walls are prob and reinforced as needed
using Silicone Mastic.



All corners and pipe penetrations are being sealed using Silicone
Mastic.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879

SolarEx

ADURA
CORONA CA

Expansion joints and sheet metal counter flashing is being reinforced with Silicone mastic.



This section of the roof is now ready for Silicone coating.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879

SolarEx

ADURA
CORONA, CA

All curbs and penetrations have been reinforced using Silicone Mastic.



All drains and through wall scuppers have been resealed & reinforced using Silicone mastic.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879


SolarEx

ADURA
CORONA, CA

Corners of the roof hatch has been properly sealed with Silicone mastic.



Small units have been resealed and reinforced using a three-course flashing.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ


Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879




ADURA
CORONA, CA

Corners of all skylight curbs have been cleaned, primed sealed
with Silicone mastic and coated.



All skylights are sealed properly.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ


Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879

SolarEx

ADURA
CORONA, CA

All duct work has been cleaned, primed sealed and coated.



Duct work has been properly sealed.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
CORONA, CA

All through roof penetrations have been properly sealed and coated.



Silicone coating has been applied over this area at a rate of three gallons per every 100 square feet.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
CORONA, CA

Coating the existing roof system with Silicone.



All drains and through wall scuppers have been properly sealed and coated.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879




ADURA
CORONA, CA

Drains have been reinforced using Silicone mastic and then coated.



Scupper drains have been sealed and coated.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
CORONA, CA

All expansion joints at the parapet walls have been reinforced
with Silicone mastic and coated.



Completed Silicone roof system.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ


Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
CORONA, CA

Completed Silicone roof system.



Completed Silicone roof system.



20 Year SolarEx Silicone Restoration System

2.5 GAL Silicone/SQ – 1.0 GAL Acrylic Primer/SQ

Silicone Mastic All Details & Penetrations on Built-Up Roofing Cap Sheet

15,000 sq ft Commercial Building - Corona CA 92879



ADURA
CORONA, CA

Completed Silicone roof system.



Completed Silicone roof system.

